




# Journal of Advanced Research in Experimental Fluid Mechanics and Heat Transfer

<http://www.akademiabaru.com/submit/index.php/arefmht>  
ISSN: 2756-8202



## The Application of Infrared Thermography for Enhancing Maintenance in Public University

Intan Asila Zulkifli<sup>1</sup>, Nuzaihan Aras Agus Salim<sup>1, \*</sup>

<sup>1</sup> School of Housing, Building and Planning, Universiti Sains Malaysia, 11800, Penang, Malaysia

### ARTICLE INFO

### ABSTRACT

A university's main function is to produce quality graduates, and in doing so, university buildings do play significant roles and are vital assets and resources. Hence, to prolong a university building lifecycle to ensure all university activities to continue performing at an optimum level, building maintenance management is central. Even though several previous studies have been conducted in this area, university buildings maintenance is still viewed as insignificant. The research about utilization of infrared thermography in term of maintenance in public universities is still lacking. The objective of this research to provide recommendations for area within the public universities that can benefit from the application of infrared thermography to enhance maintenance. The research method used in this research is a qualitative method. Three public universities that was established for more than 50 years were chosen as case studies. The data was collected through narrative review and the data was then analysed. The findings highlight the benefits of implementing infrared thermography in older building maintenance within public universities, particularly in improving energy efficiency and identifying hidden issues such as moisture intrusion and structural defects. The study emphasizes the importance of timely maintenance actions based on infrared thermography assessments to reduce energy consumption and apply predictive maintenance strategies. By conducting in-depth analyses at three established public universities in Malaysia, the researchers demonstrate the effectiveness of infrared thermography in enhancing maintenance practices and prolonging the lifecycle of university buildings.

#### Keywords:

Infrared thermography; enhancing maintenance; public university

Received: 12 Jan. 2024

Revised: 26 April 2024

Accepted: 26 May 2024

Published: 24 June 2024

## 1. Introduction

Maintenance practices are essential in every building to ensure the long-term durability and optimal performance of the building. Infrared thermography, which can also be referred to as thermal imaging, is non-invasive testing method that use infrared radiation to capture and analyze the thermal patterns of surfaces. It is involved the use of thermal cameras to capture radiation that emitted by materials and then translate the images into temperature color coded images [1]. The application of infrared thermography is significant for the improvement of maintenance practices in Malaysian building as research stated that previous studies have highlight that maintenance practices

\* Corresponding author.

E-mail address: [nuzaihanaras@usm.my](mailto:nuzaihanaras@usm.my)

<https://doi.org/10.37934/arefmht.16.1.110>

in Malaysian building are inefficient and performed far below maintenance best practices with issues categorized into planning, management, staff, competency, technology and technical capabilities [2]. This research will be focused on infrared thermography and public universities since there are lack of technology integration like infrared thermography in maintenance at public universities. Many research on the utilization of infrared thermography are focusing on heritage building as the case study so there is an insufficient research in regards the application of infrared thermography in public universities case studies. This research will focus on infrared thermography and public universities since there is lack of technological integration like infrared thermography in maintenance at public universities.

## **2. Literature Review**

### *2.1 Introduction*

One of the innovative technologies that have been proven to be effective for the maintenance utilization is infrared thermography. Infrared thermography, also known as thermal imaging, is a non-invasive and non-destructive technology that uses infrared radiation to capture and analyze the thermal patterns of surfaces. Infrared thermography is categorized as a non-invasive testing method (NDT) according to the international standards [3]. To detect infrared radiation emitted by the structure surface and objects surface, it involves the use of infrared thermography to assess the variation in temperature. This also process includes measuring the release of energy, in the form of radiation, from an object and then converting that distribution into an image [4]. The historical development and evolution of infrared thermographic technology is due to the remarkable advancements of the technology in various fields such as the medical and construction field. The development of infrared thermography is initially for medical purposes but after much research revealed the versatility of that infrared thermography, it has been evolved into variety of valuable tool in fields, such as material science and industrial maintenance. Infrared thermography can be utilized for the assessment of building materials, identify and describe flaws in reinforced concrete and monitor the heating process during construction [5,6]. Structural monitoring such as the examination of constructive components in buildings and concrete bridges can be applied by infrared thermography [7]. Infrared thermography has become a popular instrument for a non-invasive inspection technique in building because it does not demand physical infiltration or damages to the building envelope. Infrared thermography is a non-intrusive testing technique that has the capability to swiftly and remotely identify issues in the building which make it acquired prevalent acceptance in the construction industry [8].

### *2.2 The Application of Infrared Thermography*

Infrared thermography has been applied widely across various fields for various purposes. Infrared thermography has become an essential non-destructive technique that is used in building inspection to detect any hidden defects [9]. It enables the identification of the potential issues since hidden defects typically cause a disturbance in the heat flow which then generates differences in temperature on the surface of the object [10]. If the object has a defect, the defect will have a periodic effect on the surface temperature distribution above it, even at low peaks. As a result, there will be a phase difference between the defective and non-defective areas [11]. Infrared thermography also relies on infrared sensors for detecting and measuring variations in thermal energy that objects emit. It is involved the use of thermal cameras to capture the radiation that emitted by materials and then translate the images into temperature color coded images [1]. The

abnormal temperature changes in the images captured by the thermal cameras can indicate the presence of cracks, humidity, heat and other surface damage [12]. One of the important applications of infrared thermography is in the field of maintenance practices which the public university infrastructure can benefit from the application of infrared thermography because it provides an accurate surface temperature and temperature contrast information which can be used to diagnose the mechanical and technical condition of the buildings.

### *2.3 The Maintenance Practices in Public Universities*

To ensure the longevity and functionality of the public university's infrastructure, it is crucial to apply the maintenance strategies at the institution. There are several studies that have been focused on improving the maintenance management practices and the benefit to public education institutions. The application of infrared thermography is important for the improvement of maintenance practices in public universities as research stated that Malaysian building maintenance practices are inefficient and below best practices, with issues categorized into planning, management, staff, competency, technology, and technical capabilities [2]. Study has emphasized that the overall maintenance costs can be reduced and the reliability and availability of equipment in the laboratory can be increased after the contribution of maintenance plans in public universities [13]. A systematic review of building maintenance practices has been conducted that highlights the need to address maintenance issues and their effects, to improve the professional maintenance practices. These studies highlight all the significance of comprehending maintenance practices and the maintenance issues which can be fundamental for improvement of maintenance in public universities [14].

### *2.4 Advantages of Infrared Thermography*

Infrared thermography has shown variable benefits and advantages after the implementation of it. The first obvious advantage and the role of infrared thermography is that infrared thermography can detect hidden defects within a building without the need to damage and penetrate the building structure. Infrared thermography is advantages for building investigations because it can detect an early defect related to building insulation such as air leakage and moisture that is not visible and cannot be seen with naked eyes which make it difficult to localize. This can allow for timely measures and action to be taken to reduce energy consumption and apply predictive maintenance. The study stated that infrared thermography is effective to identify cracks and defects in building envelopes which can allow for assessment of damage levels and indicated the necessary maintenance strategies [15]. Infrared thermography has proven effective and has a lot of advantages and potential for wide applications in various fields. It is worthy and novel to use infrared thermography for the preventative maintenance at public university. Infrared thermography has a lot of advantages and potential for broad applications in many fields and it is worthy and novel to use infrared thermography in the management of public university maintenance. Infrared thermography enables preventive maintenance and promotes sustainability in public universities by detecting any anomalies in the mechanical and electrical systems that could lead to larger system breakdowns. Other than that, infrared thermography also contributes to the sustainable public university buildings design as it detects thermal bridges and insulation discontinuities which plays an important role in energy consumption of a building.

## **2.5 Challenges and Limitations of Infrared Thermography**

Despite the numerous advantages of infrared thermography, it does possess some challenges and limitations that should be considered when utilizing it. The first limitations that all researchers have been considering when conducting an experiment using infrared thermography are the environmental factors. The accuracy and reliability of the result from infrared thermography can be manipulated by environmental factors. The actual temperature of the fault area can be affected by environmental factors such as wind speed and ambient temperature of the areas [16]. Another challenge lies in the fact that the accuracy of surface temperature measurements can be influenced by sources of error that thermographers do not fully comprehend. These errors can lead to inconsistency between stationary and dynamic thermography observations [17]. In addition, when the operators of infrared thermography lack experience, the interpretation of the result from the thermal images can be prone to significant errors [18]. There are also limitations in the existing infrared thermography techniques used for measuring resistance that might hinder their practical application [19]. Infrared thermography has shown some advance potential in assessing building condition, detecting building flaws and defects despite all the challenges and limitations. In order to address this limitation of infrared thermography, researchers have proposed a variety of advancements. For example, to overcome certain limitations, an extension of the differential infrared thermography (DIT) method has been considered [20]. The use of infrared thermography in buildings is promising with potential applications in predictive maintenance and energy efficiency.

## **3. Methodology**

Research methodology is crucial in doing research as it is a way of explaining how a researcher intends to carry out their research. It is a logical approach to resolve a research problem. Research methodology describes the researcher's approach to the research to produce reliable and valid results that fulfil the researcher's aim and objectives. This research methodology will specify what data will be gathered and where it will be collected as well as how it will be collected and analyzed. This research topic is related to the application of infrared thermography for enhanced maintenance and sustainability in public universities and this research will be conducted specifically at the lecture hall at academic buildings in public universities. This section will present the explanation for the research design and research approach that the researcher plans on employing for this study. The researcher's role and how it might affect the study are also highlighted. The last part of the chapter will discuss the study's research questions, sample, data collection, and how the researcher plans to establish the trustworthiness of the research.

### **3.1 Data Collection Methods**

Data collection is an important process of collecting and evaluating data to find the answers to research questions. The research objective 3 is to provide recommendations for area within the public universities that can benefit from the application of infrared thermography to enhance maintenance. The type of data collection method that will be used for this research objective is qualitative method which is narrative review. The results obtained from the data will be analyzed and summarized into the specific topic that will support the data of this research.

### **3.1.1 Case study**

A case study is a type of qualitative research approach that entails an inquiry into specific person, group, organization, event or phenomenon to conduct an in-depth analysis of the subject (Sturman, 1997). There is total of three public universities in Malaysia that have been chosen as the case studies. The reason for the selection of case study is all three case studies was established for more than 50 years which can indicate the public university is an old building.

### **3.1.2 Narrative review**

The data collection method for research objective 3 is narrative review. The narrative review highlights the significant role of infrared thermography in building maintenance, especially in preventive maintenance. It outlines various applications and benefits of infrared thermography emphasizing its utility in identifying hidden issues like moisture intrusion and assessing the condition of aging structures. The review references multiple studies to underscore the versatility and effectiveness of infrared thermography in maintenance practices.

## **4. Data Analysis**

The data from collected literature was categorized into different potential application areas of infrared thermography within public universities. Each category was analysed to determine the benefits that associate with the implementation of infrared thermography in public universities.

### **4.1 Older Building Maintenance**

All three public universities which are the public university A, public university B and public university C can implement infrared thermography for the maintenance in older building within the public universities. The public universities can enhance its maintenance by improving energy efficiency in older building. Infrared thermography can be utilized for the inspection of historical buildings and cultural heritage sites which enables the study of building structures, identification of hidden element and the assessment of damages cause by aging or environmental factors [no][no]. All three public universities were established for more than 50 years which can indicated it is an old building. Many of the building at the three public universities are established in the 1960s and 1970s and this is the reason why the building faced significant wear and tear. It needs proper maintenance because the lack of maintenance strategy combined with natural aging accelerates the deterioration of building structure [1].

### **4.2 Building Envelope**

For building envelope application, infrared thermography is the most effective in detecting hidden defects such as moisture intrusion. Research has emphasized the role of infrared thermography in evaluating building envelope air leakage, showcasing its potential as a forensic tool for assessing the thermal performance of building envelopes [17]. According to WHO (2009), it has been identified that moisture cause 75 to 80 percent of defects in building envelopes. It enables the identification of potential problems since defects typically cause a disturbance in the heat flow which generates temperature differences on the surface of the elements [10]. If the object has a defect, the defect will have a periodic effect on the surface temperature distribution above it, even at low peaks.

As a result, there will be a phase difference between the defective and non-defective areas [11]. Infrared thermography works by detecting any temperature anomalies in the areas which can be used to detect moisture surface because it has different thermal conductivity compared to dry surface. The thermal conductivity of water is higher than the dry building materials and when there is water in the pores of these materials, the thermal conductivity will increase, and thermal resistance will be lower [10]. Based on the observation at each case studies, the most common defects that can be found is related to moisture intrusion. Defects caused by moisture intrusion can be seen at building envelope at public universities such as there is mould growth especially at the exterior wall of public universities restroom. Infrared thermography can detect moisture areas with precision, recall and accuracy around 83.5%, 73.5% and 72.5% in concealed areas of building structures [5]. Infrared thermography enables quick and efficient scanning of large areas which can reduce the inspection time in comparison with traditional methods [11]. Infrared thermography also enables the detection of moisture intrusion that are not visible naked eye, making it a valuable tool for identifying hidden defects within the building envelopes [21].

#### *4.3 Mechanical and Electrical Systems*

Maintaining mechanical and electrical systems is important for the efficiency in operation and by implementing infrared thermography can offer significant advantages. Infrared thermography has shown promise for non-destructive evaluation of composite bonding structures used in electrical insulation [22]. The application of infrared thermography can be utilized in early fault detection in the mechanical and electrical systems at public universities which can prevent costly breakdowns. Infrared thermography can be utilized for solar panel systems. Infrared thermography, renowned for its non-destructive testing capabilities, can effectively detect anomalies and defects in solar panels by measuring temperature variations [23].

All three cases have implemented several solar panel systems across its campuses to harness renewable energy, reduce carbon emissions and serves as a practical demonstration for students and researchers. These solar panels are installed on the rooftops of key buildings including the engineering faculties at each case studies. For electric power systems, infrared thermography has become an effective tool due to its high precision and non-intrusiveness in the field of preventive maintenance [24]. By detecting potential hazards such as overheating components or electrical arcing, infrared thermography helps in enhancing safety measures for maintenance personnel and preventing accidents [1]. Infrared used to inspect solar panels by identifying hotspots and defective cells which ensures optimal performance of renewable energy systems installed at the case studies.

#### *4.4 Energy Audits*

Energy audits facilitated by infrared thermography can identify areas of heat loss and energy inefficiencies in public university buildings. Infrared thermography can aid in conducting energy audits by providing insights into heat losses through building envelope [25]. Infrared thermography can detect insulation leaks. The implementation of infrared thermography in building energy audits is to identify any thermal defects that happen such as the thermal bridging, insulation level and air leakage [26]. Any areas for improvement, to reduce the energy consumption in building, can be identified by conducting an energy audit.

The improvement of sustainability of HVAC systems can help in providing health and comfort for the occupants, improved energy efficiency and reduced the environmental impact which is significant for the building [27]. Infrared thermography can evaluate variety of building material. This have

evident to be effective in the detection of moisture in various building materials, which can help in identify the areas affected by moisture that can contribute to energy loss [5]. The role of infrared thermography is that it can detect thermal bridges and energy loss due to lack of insulation in building, which can use to evaluate the building envelope [28]. By implement the use of infrared thermography in maintenance can ensure energy efficiency and better maintenance and sustainability practices in public universities.

**Table 1**

Summary area for the application of infrared thermography within public universities

Area of application	Benefits	References
Older building maintenance	Improves energy efficiency in older buildings	Cadelano <i>et al.</i> , [25]
	Enables inspection of historical and cultural heritage sites	
	Identifies hidden elements and assesses damage caused by aging or environmental factors	
Building envelope	Defects hidden defects such as moisture intrusion	WHO (2009), Dafico <i>et al.</i> , [10], Qu <i>et al.</i> , [11], Garrido <i>et al.</i> , [5], Vazquez & Thomachot-Schneider [21]
	Identifies potential problems via temperature differences	
	Detects moisture areas with high precision, recall and accuracy	
	Reduces inspection time compared to traditional methods	
	Identifies hidden defects not visible to the naked eye	
Mechanical and electrical systems	Offers non-destructive evaluation of composite bonding structures in electrical insulation	Guo [22]
	Detects early faults in mechanical and electrical systems to prevent costly breakdowns	
	Monitors solar panel systems for anomalies and defects	
	Enhances safety measures by detecting overheating components or electrical arching	
Energy audits	Identifies areas of heat loss and energy inefficiencies	Cadelano <i>et al.</i> , [25], Lucchi [26], Asim <i>et al.</i> , [27], Garrido <i>et al.</i> , [5]
	Detects insulation leaks and thermal defects	
	Improves sustainability of HVAC systems	
	Evaluates thermal bridges and energy loss due to lack of insulation	
	Ensures energy efficiency and better maintenance and sustainability practices	

Table 1 shows the primary areas where infrared thermography can be applied within public universities and highlighting its benefits with supporting references for each application.

## 5. Results and Discussion

### 5.1 To Provide Recommendations for Area within the Public Universities that Can Benefit from the Application of Infrared Thermography to Enhance Maintenance

Several studies have emphasized the effectiveness of infrared thermography in detecting building envelope leaks and insulation deficiencies. This application of infrared thermography can aim to reduce energy consumption and maintenance costs as well as improving environmental sustainability

in public universities. Infrared thermography also widely utilized for electrical system inspection. This area of application can minimize the risk of electrical failures and optimizing the campus safety which is significant for large public institutions. Predictive maintenance of HVAC systems using infrared thermography can enables public universities to plan maintenance schedules efficiently. This proactive approach helps in preventing system breakdowns and ensuring optimal maintenance performance.

**Table 2**  
 Key findings and the relevance to public universities

Study	Key findings	Relevance to Public Universities
Mahmoodzadeh [17]	Application of infrared thermography in detecting building envelope leaks	Reducing energy consumption, costs and improving sustainability in university campuses
Parashar [20]; Muttillio <i>et al.</i> , [14]	Use of infrared thermography for electrical system inspections	Enhancing safety and reducing downtime in campus infrastructure.
Venegas <i>et al.</i> , [29]; Bauer <i>et al.</i> , [23]	Infrared thermography in predictive maintenance of HVAC systems	Cost-effective maintenance planning for university facilities

The findings suggest that infrared thermography can be an effective tool that can be utilized in many areas within the public universities that includes old building area, building envelopes, mechanical and electrical systems and energy audits. The narrative review indicates that infrared thermography is a versatile tool with multiple applications in public universities. Facility maintenance emerges as the most frequently mentioned application. Infrared thermography has a lot of potential in preventing costly breakdowns which can enhance the public universities maintenance as well as safety. Energy efficiency is another critical area where infrared thermography can provide substantial savings by identifying thermal inefficiencies. The implementation of infrared thermography in public universities faced challenges in terms of budget and cost such as the initial cost of infrared thermography equipment and the cost need for trained personnel to interpret thermal images accurately. However, by implementing infrared thermography as a predictive maintenance tool has the potential for optimizing the maintenance costs [29]. Integrating infrared thermography with existing systems can ensure the detection of maintenance issues within the public universities at an early stage which can lead to cost savings.

## 6. Recommendation

The area of application that can benefit from the application of infrared thermography at the three case studies is at older buildings maintenance. By implementing infrared thermography, public universities can gain many benefits from its applications. Implement routine infrared thermography for all campus building in the public universities. Additionally, utilizing infrared thermography aligns with the trend towards predictive maintenance, where maintenance activities are scheduled based on equipment condition rather than fixed time intervals [29]. Infrared thermography has shown the effectiveness for enhancing maintenance practices in public universities. Public universities can conduct predictive maintenance after the implementation of infrared thermography. Public universities commonly rely on proactive maintenance rather than predictive maintenance. By implement infrared thermography, public universities can swift from corrective maintenance to predictive maintenance which can leads to enhancing maintenance practices. Preventive maintenance has been recognized as a critical aspect of building management to prevent



deterioration, ensure safety and maintain comfort for building occupants. This can be supported by research that proper maintenance can save the energy ranging from 1.62% to 25% with the additional advantages such as lower emissions, restored production capacity, higher availability and higher reliability [30]. By analysing infrared thermographic data over time, trends can be identified, and predictive maintenance schedules can be established based on the historical performance of electrical systems [1].

## 7. Conclusions

In conclusion, through case studies and narrative reviews, the researchers have provided valuable insights into the benefits of utilizing infrared thermography in building maintenance practices at public universities. The findings underscore the role of technology in enhancing maintenance strategies and optimizing the operational efficiency of educational institutions. This research contributes to the body of knowledge on maintenance management in public universities and provides practical recommendations for the implementation of infrared thermography in current maintenance practices. By embracing preventive maintenance approaches and leveraging advanced technologies like infrared thermography, public universities can strive towards achieving sustainable and world-class facilities for the benefit of students, faculty, and staff.

## References

- [1] Busheska, Angela, Nicholas Sabella, Nara Almeida, and Eudes Rocha. "Machine Learning and Thermography Applied to the Detection and Classification of Cracks in Buildings." In *2023 IEEE Conference on Technologies for Sustainability (SusTech)*, pp. 247-251. IEEE, 2023.
- [2] Sarbini, Noor Nabilah, Izni Syahrizal Ibrahim, Nur Izieadiana Abidin, Fadzil Mat Yahaya, and Nik Zainab Nik Azizan. "Review on maintenance issues toward building maintenance management best practices." *Journal of Building Engineering* 44 (2021): 102985.
- [3] Glavaš, Hrvoje, Držislav Vidaković, and Igor Sušenka. "Infrared thermography in steam trap inspection." *Journal of Energy: Energija* 70, no. 3 (2021): 3-7.
- [4] Diz-Mellado, Eduardo, Emilio J. Mascort-Albea, Rocío Romero-Hernández, Carmen Galán-Marín, Carlos Rivera-Gómez, Jonathan Ruiz-Jaramillo, and Antonio Jaramillo-Morilla. "Non-destructive testing and Finite Element Method integrated procedure for heritage diagnosis: The Seville Cathedral case study." *Journal of Building Engineering* 37 (2021): 102134.
- [5] Garrido, Iván, Susana Lagüela, Stefano Sfarra, F. J. Madruga, and Pedro Arias. "Automatic detection of moistures in different construction materials from thermographic images." *Journal of Thermal Analysis and Calorimetry* 138 (2019): 1649-1668.
- [6] Chen, Wei, Kesen Wei, Jincheng Wei, Wenyang Han, Xiaomeng Zhang, Guiling Hu, Shuaishuai Wei et al. "Research on the road performance of asphalt mixtures based on infrared thermography." *Materials* 15, no. 12 (2022): 4309.
- [7] Farmaki, Spyridoula, Dimitrios A. Exarchos, Ilias K. Tragazikis, Theodore E. Matikas, and Konstantinos G. Dassios. "A novel infrared thermography sensing approach for rapid, quantitative assessment of damage in aircraft composites." *Sensors* 20, no. 15 (2020): 4113.
- [8] Usamentiaga, Rubén, and Pablo Venegas. "Infrared Imaging and NDT." *Applied Sciences* 11, no. 7 (2021): 3024.
- [9] Zhai, Yu, Chuanxiang Gao, Xi Chen, and Ben M. Chen. "An Application of Thermography in Building Facade Inspection based on YOLOv3." In *2022 International Conference on Computer and Drone Applications (IConDA)*, pp. 131-136. IEEE, 2022.
- [10] Dafico, Leticia CM, Eva Barreira, Ricardo MSF Almeida, and Helena Carasek. "Comparison of infrared thermography and other traditional techniques to assess moisture content of wall specimens." *Sensors* 22, no. 9 (2022): 3182.
- [11] Qu, Zhi, Peng Jiang, and Weixu Zhang. "Development and application of infrared thermography non-destructive testing techniques." *Sensors* 20, no. 14 (2020): 3851.
- [12] Gil-Docampo, Mariluz, Juan Ortiz Sanz, Ignacio Cañas Guerrero, and Manés Fernández Cabanas. "UAS IR-Thermograms processing and photogrammetry of thermal images for the inspection of building envelopes." *Applied Sciences* 13, no. 6 (2023): 3948.

- [13] Madruga, Francisco J., Stefano Sfarra, Eusebio Real, Gianfranco Gargiulo, Olga M. Conde, and Jose M. López-Higuera. "Complementary use of active infrared thermography and optical coherent tomography in non-destructive testing inspection of ancient marquetries." *Journal of Nondestructive Evaluation* 39 (2020): 1-8.
- [14] Muttillio, Mirco, Iole Nardi, Vincenzo Stornelli, Tullio de Rubeis, Giovanni Pasqualoni, and Dario Ambrosini. "On field infrared thermography sensing for PV system efficiency assessment: Results and comparison with electrical models." *Sensors* 20, no. 4 (2020): 1055.
- [15] Moga, Ligia, I. Moga, T. Şoimoşan, Ioana Moldovan, M. Rădulescu, A. Rădulescu, and Ionut Iancu. "Infrared thermography application for in-situ determination of the building envelope thermal performance." In *Journal of Physics: Conference Series*, vol. 2654, no. 1, p. 012122. IOP Publishing, 2023.
- [16] Ma, Jianchao, Hanbo Zheng, Yonghui Sun, Zhuo Zhang, Xiaohui Wang, Guojun Ding, Lei Guo, and Chaohai Zhang. "Temperature compensation method for infrared detection of live equipment under the interferences of wind speed and ambient temperature." *IEEE Transactions on Instrumentation and Measurement* 70 (2021): 1-9.
- [17] Mahmoodzadeh, Milad, Voytek Gretka, and Phalguni Mukhopadhyaya. "Challenges and opportunities in quantitative aerial thermography of building envelopes." *Journal of Building Engineering* 69 (2023): 106214.
- [18] Martinez, I., and E. Martinez. "Qualitative timber structure assessment with passive IR thermography. Case study of sources of common errors." *Case Studies in Construction Materials* 16 (2022): e00789.
- [19] Tejedor, Blanca, Elena Lucchi, and Iole Nardi. "Application of qualitative and quantitative infrared thermography at urban level: Potential and limitations." In *New Technologies in Building and Construction: Towards Sustainable Development*, pp. 3-19. Singapore: Springer Nature Singapore, 2022.
- [20] Parashar, S., kumar, A., sharma, P., rana, S., & kumar, D. (2023). Fault prediction in electrical assets using infrared thermography. *Journal of Physics: Conference Series*, 2570(1), 012019
- [21] Vazquez, P., and C. Thomachot-Schneider. "Infrared thermography as a tool to detect increasing cracking in granitic stones exposed to high temperatures." *Journal of Cultural Heritage* 59 (2023): 163-170.
- [22] Guo, Chenjun, Lishuai Liu, Hongwei Mei, Yanxin Tu, and Liming Wang. "Nondestructive evaluation of composite bonding structure used in electrical insulation based on active infrared thermography." *Polymers* 14, no. 16 (2022): 3373.
- [23] Bauer, Joanna, Md Nazmul Hoq, John Mulcahy, Syed AM Tofail, Fahmida Gulshan, Christophe Silien, Halina Podbielska, and Md Mostofa Akbar. "Implementation of artificial intelligence and non-contact infrared thermography for prediction and personalized automatic identification of different stages of cellulite." *EPMA Journal* 11, no. 1 (2020): 17-29.
- [24] Qureshi, Usamah, Aiman Rashid, Nicola Altini, Vitoantonio Bevilacqua, and Massimo La Scala. "Radiometric Infrared Thermography of Solar Photovoltaic Systems: An Explainable Predictive Maintenance Approach for Remote Aerial Diagnostic Monitoring." *Smart Cities* 7, no. 3 (May 28, 2024)
- [25] Cadelano, Gianluca, G. Ferrarini, Alessandro Bortolin, and Paolo Bison. "Mapping large surfaces of cultural heritage buildings by infrared thermography." In *Journal of Physics: Conference Series*, vol. 2204, no. 1, p. 012082. IOP Publishing, 2022.
- [26] Lucchi, Elena. "Applications of the infrared thermography in the energy audit of buildings: A review." *Renewable and Sustainable Energy Reviews* 82 (2018): 3077-3090.
- [27] Asim, Nilofar, Marzieh Badiei, Masita Mohammad, Halim Razali, Armin Rajabi, Lim Chin Haw, and Mariyam Jameelah Ghazali. "Sustainability of heating, ventilation and air-conditioning (HVAC) systems in buildings—An overview." *International journal of environmental research and public health* 19, no. 2 (2022): 1016.
- [28] Zakaria, Azzarina, and Stephen A. Zurcher. "An Analysis of Sustainability Approaches of Malaysian Public Universities." *Environment-Behaviour Proceedings Journal* 8, no. 23 (2023): 201-206.
- [29] Venegas, Pablo, Eugenio Ivorra, Mario Ortega, and Idurre Sáez de Ocáriz. "Towards the automation of infrared thermography inspections for industrial maintenance applications." *Sensors* 22, no. 2 (2022): 613.
- [30] Firdaus, Nofirman, Hasnida Ab-Samat, and Bambang Teguh Prasetyo. "Maintenance strategies and energy efficiency: a review." *Journal of Quality in Maintenance Engineering* 29, no. 3 (2023): 640-665.